

▶ 滑块垫片检验  
Checking for Gliding Plates and Washers

测量对象 Checking Items	测量方法 Checking Methods	测量工具 Checking Equipments
长度, 宽度 Length, Width	用游标卡尺测量 Measure with Vernier Calipers	游标卡尺 Vernier Calipers
	对环形垫片测量内外径。若是两个半圈, 则需将垫片拼接成圆, 用游标卡尺测量内、外径尺寸 The inner and outer diameters of the annular washer are measured. If the thrust are two half-ring, we need joint to measure the inner diameter.	游标卡尺 Vernier Calipers
厚度 Thickness	用游标卡尺测量 Measure with Vernier Calipers	壁厚千分尺 Micrometer for Wall Thickness Checking  游标卡尺 Vernier Calipers
孔径 Bore Diameter	内径千分尺 Measure with micrometer for I.D. checking	内径千分尺 Micrometer for I.D. Checking  游标卡尺 Vernier Calipers
孔距 Bore Gap	用游标卡尺测量 Measure with Vernier Calipers	游标卡尺 Vernier Calipers